

## FAN COIL UNIT MOTORS DIRECTLY COUPLED


#### **CODE 0402408** MOTOR 83-2025/01



CODE 0402409


MOTOR 83-2025/3







| V    | HZ | A V  | / OUTPU | T W ABS | . N° SPE | EDS  | rpm | В   | C    | D  | E     | Ø       | €      |
|------|----|------|---------|---------|----------|------|-----|-----|------|----|-------|---------|--------|
| CODE |    |      |         |         |          |      |     |     |      |    | SHAFT |         |        |
| 230  | 50 | 0.46 | 25      | 100     | 4        | 1100 | 74  | 106 | 53.5 | 20 | 9.52  | 0402408 | 120,00 |
| 230  | 50 | 0.36 | 25      | 90      | 6        | 1100 | 71  | 106 | 53.5 | 20 | 9.52  | 0402409 | 126,00 |
| 230  | 50 | 0.48 | 28      | 64      | 4        | 1100 | 79  | 135 | 53.5 | 40 | 9.52  | 0402410 | 120,00 |


# **CODE 0402410** MOTOR 83M-2521/01



### **CODE 0402411** MOTOR 83-2015/08







| v       | Hz | A    | A W Output W Ass. |    | N° Speeds | rpm  | Ø Shaft | CODE    | €      |
|---------|----|------|-------------------|----|-----------|------|---------|---------|--------|
| 220/240 | 50 | 0.23 | 13                | 50 | 3         | 1100 | 9.52    | 0402411 | 112,00 |
|         |    |      |                   |    |           |      |         |         |        |

### DESCRIPTION:

Spare motor for centrifugal fans installed mainly in fan coil ventilation units.

